

**From:** [Dan Ciarcia](#)  
**To:** [Maura Weissleder](#)  
**Subject:** RE: 24-5 - Rotating Biological Contactors Bearing Replacement  
**Date:** Wednesday, August 28, 2024 9:20:37 AM  
**Attachments:** [image001.png](#)

---

Maura:

The shaft diameter is 4.94"

Dan Ciarcia, P.E.  
Town Engineer  
Town of Yorktown  
363 Underhill Avenue  
Yorktown Heights, NY 10598  
(914) 962-5722 x218

---

**From:** Maura Weissleder <[mauraw@yorktownny.org](mailto:mauraw@yorktownny.org)>  
**Sent:** Wednesday, August 21, 2024 3:16 PM  
**To:** Dan Ciarcia <[dciarcia@yorktownny.org](mailto:dciarcia@yorktownny.org)>  
**Subject:** FW: 24-5 - Rotating Biological Contactors Bearing Replacement  
**Importance:** High

Please respond to me for the below and I'll post. Thanks.

---

**From:** Anthony Kennard <[akennard@beardsleetransmission.com](mailto:akennard@beardsleetransmission.com)>  
**Sent:** Wednesday, August 21, 2024 11:48 AM  
**To:** Maura Weissleder <[mauraw@yorktownny.org](mailto:mauraw@yorktownny.org)>  
**Subject:** 24-5 - Rotating Biological Contactors Bearing Replacement  
**Importance:** High

**CAUTION:** This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Good morning

May I please get the shaft size for the pictures below? So I can give you an accurate price on the housing and insert bearing? This is in regards to Bidnet posting



TYPICAL DRIVE BEARING

2  
←  
J



TYPICAL IDLER BEARING



IDLER RBC-2E

Thank you and have a great day.

Anthony Kennard

**Beardslee Transmission Equipment Co., Inc.**

290 East Jerhico Turnpike

Mineola, N.Y. 11501

Office: (516) 747-5557

[BeardsleeTransmission.com](http://BeardsleeTransmission.com)

